


MOD: Polar



MEDIDAS DE CONTROL DE PRENDAS TERMINADA



| MEDIDAS(mm) | ref. | T0 | T1 | T2 | T4 | T6 | T8 | T10 | T12 | T14 | T16 | T18 | T20 | T22 | T24 | T26 |
|--------------|------|-----|-----|-----|-----|-----|-----|-----|-----|-----|-----|-----|-----|-----|-----|-----|
| Largo cuerpo | A | 340 | 380 | 420 | 460 | 500 | 530 | 570 | 600 | 620 | 630 | 650 | 670 | 700 | 720 | 750 |
| Contorno | B | 290 | 320 | 350 | 380 | 410 | 450 | 480 | 500 | 520 | 540 | 550 | 560 | 580 | 600 | 620 |
| Largo Manga | C | 320 | 360 | 410 | 460 | 510 | 560 | 610 | 640 | 670 | 700 | 710 | 730 | 770 | 800 | 830 |
| Espalda | D | 230 | 250 | 270 | 300 | 340 | 370 | 410 | 430 | 450 | 470 | 480 | 490 | 510 | 540 | 550 |

OBSERVACIONES: